



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-2043/1

Work Order Type: Weatherization

Audit Name: Audit (115)

CLIENT INFORMATION

Client Name: N/A

Address:

Client ID: 17017UC-2043

Alt. Client ID: SMITH

CLIENT CONTACT INFORMATION

N/A

Applicant/Person of Record

AGENCY INFORMATION

Agency: Upper Cumberland Human Resource Agency

Agency Phone: (931) 528-1127

Address: 580 South Jefferson Avenue, Suite B
Cookville, TN 38501

Fax: (931) 526-8305

Email Address:

Agency Contact: Smith, Richmond

Work Phone:

Cell Phone:

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

HOME BUILT IN 1962

AUDITOR : RICHMOND SMITH

Measures

Measure 1 Infiltration Redctn

Components

Inspected

Comment REPLACE DR1 & DR2 W/INSULATED STEEL UNITS AND ALL NEW HDWE. REPLACE DR3 & DR4 W/INS. STEEL HINGED PATIO DOOR UNITS. GLAZE & CAULK INT. & EXT. OF ALL 13 WINDOWS.

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Su	Infiltration Reduction	Each	1	<input type="text"/>				

Other Detail

<input type="text"/>									
<input type="text"/>									

Measure Sub Total: Sub Total:

Field Notes:

Measure 2 User-Spec Ceiling R

Components ATC1

Inspected

Comment BUILD OVER PULL DOWN STAIRWAY

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Cellulose, Blown - R-38	SqFt	1160	<input type="text"/>				
2	Labor	Attic Insulation - Cellulose, Blown - R-38	SqFt	1160	<input type="text"/>				
3	Miscellaneous Su	Added Misc Cost - Cellulose, Blown - R-38	Each	1	<input type="text"/>				

Other Detail

<input type="text"/>									
<input type="text"/>									

Measure Sub Total: Sub Total:

Field Notes:

Measure 3 Lighting Retrofits

Components L1,L2

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Lighting	Compact FI. - 13 Watt	Each Lamp	3	<input type="text"/>				
2	Labor	Compact FI. - 13 Watt	Each Lamp	3	<input type="text"/>				
3	Lighting	Compact FI. - 13 Watt	Each Lamp	3	<input type="text"/>				
4	Labor	Compact FI. - 13 Watt	Each Lamp	3	<input type="text"/>				

Other Detail

<input type="text"/>									
<input type="text"/>									

Measure Sub Total:

Sub Total:

Field Notes:

Measure 4 DWH Tank Insulation

Components

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equip	DHW Tank Insulation	Each	1	<input type="text"/>				
2	Labor	DHW Tank Insulation	Each	1	<input type="text"/>				

Other Detail

<input type="text"/>									
<input type="text"/>									

Measure Sub Total:

Sub Total:

Field Notes:

Measure 5 DWH Pipe Insulation

Components

Inspected

Comment WRAP 6 FT HOT & COLD LINES @ W/HTR

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>				
2	Labor	DHW Pipe Insulation	Each	1	<input type="text"/>				

Other Detail

<input type="text"/>								
<input type="text"/>								

Measure Sub Total:

Sub Total:

Field Notes:

Measure 6 Floor Ins. R-19

Components F1

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1160	<input type="text"/>				
2	Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1160	<input type="text"/>				

Other Detail

<input type="text"/>								
<input type="text"/>								

Measure Sub Total:

Sub Total:

Field Notes:

Measure 8 CO Monitor is Needed

Components

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1	<input type="text"/>				
2	Labor	Labor	Each	1	<input type="text"/>				

Other Detail

<input type="text"/>								
<input type="text"/>								

Measure Sub Total:

Sub Total:

Field Notes:

Measure 9 Fix Wiring Problems (Walls)

Components

Inspected

Comment REPLACE EXISTING 200 AMP FUSEBOX W/200 AMP BREAKER BOX .

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	See the User Defined Measure for a list of materials.	Each	1	<input type="text"/>				

Other Detail

<input type="text"/>								
<input type="text"/>								

Measure Sub Total:

Sub Total:

Field Notes:

Measure 10 Install Bathroom Exhaust Fan

Components

Inspected

Comment INSTALL NEW BATH EXHAUST FAN AND VENT OUTSIDE. MAY HAVE TO PULL WIRE AND SWITCH.

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	See the User Defined Measure for a list of materials.	Each	1	<input type="text"/>				

Other Detail

<input type="text"/>								
<input type="text"/>								

Measure Sub Total:

Sub Total:

Field Notes:

Measure 11 Install Kitchen Exhaust Fan

Components

Inspected

Comment INSTALL KITCHEN EXHAUST FAN AND VENT OUTSIDE. WILL HAVE TO PULL WIRE.

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	See the User Defined Measure for a list of materials.	Each	1	<input type="text"/>				

Other Detail

<input type="text"/>								
<input type="text"/>								

Measure Sub Total:

Sub Total:

Field Notes:

Measure 12 MOVE WATER HEATER

Components

Inspected

Comment MOVE EXISTING 50 GAL ELECT WATER HEATER FROM OUTBUILDING TO INSIDE OF HOME AND HOOK UP.

#	Material / Labor	Description / Comment	Units	Estimated		Actual				
				Qty	Unit Cost	Total	Qty	Unit Cost	Total	
10	Unspecified	Misc Material	Each	1	<input type="text"/>					
Other Detail										
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
Measure Sub Total:							<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Measure 13 Smoke Detector is Needed X 2

Components

Inspected

Comment INSTALL 2 SMOKE DETECTORS

#	Material / Labor	Description / Comment	Units	Estimated		Actual				
				Qty	Unit Cost	Total	Qty	Unit Cost	Total	
10	Unspecified	See the User Defined Measure for a list of materials.	Each	1	<input type="text"/>					
Other Detail										
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
Measure Sub Total:							<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

**Measure 14 Vapor Barrier Needed
(Basement/Crawlspace)**

Components

Inspected

Comment INSTALL 1160 SQ FT GROUND COVER

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	See the User Defined Measure for a list of materials.	Each	1	<input type="text"/>				

Other Detail

<input type="text"/>								
<input type="text"/>								

Measure Sub Total:

Sub Total:

Field Notes:

Work Order Grand Total:

Grand Total: